

HABS  
ORE  
15-MED  
1A-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Medford Service Center, Warehouse (Building #220~~3~~)  
1319 McAndrews Road  
Medford  
Jackson County  
Oregon

HABS No. OR-160-A

Natalie Brown, Photographer

April 1993

- OR-160-A-1      VIEW OF WEST SIDE AND SOUTH (REAR) SIDE OF WAREHOUSE (BUILDING #2205), FACING NORTHEAST.
- OR-160-A-2      VIEW OF NORTH FRONT AND WEST SIDE OF BUILDING #2205 (AREA CONTAINING STORAGE AND EQUIPMENT SUPPLIES), FACING SOUTHEAST.
- OR-160-A-3      VIEW OF EAST SIDE AND NORTH FRONT OF BUILDING #2205 (AREA CONTAINING VEHICLE REPAIR SHOP AND VEHICLE MANAGEMENT OFFICE), FACING SOUTHWEST.
- OR-160-A-4      BUILDING #2205, INTERIOR VIEW OF VEHICLE REPAIR SHOP, FACING SOUTHEAST.
- OR-160-A-5      BUILDING #2205, INTERIOR VIEW OF UPPER STORAGE FLOOR ("ATTIC") SHOWING SKYLIGHT, FACING SOUTHEAST.
- OR-160-A-6      BUILDING #2205, INTERIOR VIEW OF UPPER STORAGE FLOOR ("ATTIC") SHOWING LIGHT ADMITTED BY MAIN BANK AND UPPERMOST WINDOWS, FACING SOUTHWEST.
- OR-160-A-7      BUILDING #2205, INTERIOR VIEW OF UPPER STORAGE FLOOR ("ATTIC") SHOWING FREIGHT ELEVATOR, FACING WEST-NORTHWEST.

Note: All photographs are 8" x 10" enlargements from 4" x 5" negatives.